





1




First, check if all parts are present.

2




Screw the top onto the ground light.

3




Drill a hole with a diameter of 51 mm at the desired location and insert the ground light into the hole. If necessary, use the supplied strike plate.

4



Now, connect the coupling piece of the ground light to the product cable connector.

5



Place the 12-volt main cable between the product cable connector and snap the connector onto the main cable. Your lighting is now ready for use.