




First, check if all parts are present.




Screw the top onto the ground light.



Drill a hole with a diameter of 25 mm at the desired location and insert the ground light into the hole. If necessary, use the supplied strike plate.



Now, connect the coupling piece of the ground light to the product cable connector.



Place the 12-volt main cable between the product cable connector and snap the connector onto the main cable. Your lighting is now ready for use.