




**1**


First, check if all parts are present.

2


Screw the top onto the ground light.

3

Drill a hole with a diameter of 51 mm at the desired location and insert the ground light into the hole. If necessary, use the supplied strike plate.

4

Now, connect the coupling piece of the ground light to the product cable connector.

5

Place the 12-volt main cable between the product cable connector and snap the connector onto the main cable. Your lighting is now ready for use.